



Photocatalytic Degradation of NOx - SELF CLEANING Surface

This photo is taken in 2005 at a toll booth in Japan. Six months after the applicaiotn of our TPXsol photocatalyst Coating.This clearly demostrates the grime preventing functionality of our photocatalytic coating.



This photo shows a white concrete panel exposed to six months of highway grime. The white squares had been coated with our TPXsol phocatalyst self cleaning coating.

