

Mold Remediation & Photocatalytic Coating Application at Carlton Hotel

The Challenge: The Carlton Hotel has been

undergoing a complete renovation. During the renovation, the owner wanted to address an area of the lower level that has had mold and odor problems for quite some time.

The Solution: The Green Millennium's Photocatalytic coating system with the PTA-85 and TPX-85 was used to provide a continuous PureZone of clean air for the entire space and to prevent the re-growth of mold. The owner reported a dramatic odor improvement the old, bad smell is entirely gone.







